110BDCP

1-1/4” 20GA P-TRAP, LESS CLEANOUT

Description:

Certification

P-TRAP SHALL BE 1-1/4” GROUND JOINT, 20 GAUGE TUBULAR BRASS, 7” BRASS WALLBEND, CHROME FINISH, BRASS NUTS, DEEP BELL FLANGE, LESS CLEANOUT,
CERTIFIED BY CSA



Oakville Stamping and Bending Ltd.
2200 Speers Road. Oakville, ON. Canada. L6L 2X8.
T. 905.827.0320 or toll free 1.877.314.6040 F. 905.827.6375 or toll free 1.877.827.6040.

All rights reserved. OS&B™ reserves the right to change product specifications and material or discontinue models without notice.

www.osb.ca